

Manual Cleaning the MF6R3

The following document is a guide from MEYTON Elektronik GmbH. This document is the property of Meyton Elektronik GmbH. It is subject to copyright. All texts and illustrations may not be used or reproduced without our express consent.

The trademarks mentioned are protected by the respective rights holders. When screenshots are distributed by Meyton Eletronik Gmbh, these can be used by the person. However Meyton Eletronik must be informed if these shall be passed to a third party. These represent the full intellectual property of their respective owners of copyright.

All copyrights of the screenshots and the thereon designs are exclusively the respective holders. The insertions made in the form of additional graphic elements exclusively serve better presentation to the user of this manual and are not part of the original screenshots.

MEYTON Elektronik GmbH

web	http://support.meyton.eu
tel	+49 5226 9824-0
mail	support@meyton.info

Content

1	CI	eaning the MF6R3BM	4
2	Ve	erification of the EST with Control-PC	5
	2.1	Calibrating the EST	5
	2.2	Reading the display during the calibration	7
3	Ve	erification of the EST with ESTA5	9
	3.1	Showing the light sensor values	9
	3.2	Reading the light sensor values	9
	3.3	Calibrating the EST 1	10
4	CI	eaning the EST 1	.1

1 Cleaning the MF6R3BM



DANGER

Lead dust

Avoid the creation of and the exposure to lead dust.

- a) Wear protective gloves, protective goggles, protective mask and suitable protective clothing.
- b)Use wet pieces of cloth for cleaning and for absorbing lead dust.
- c) Use a brush and presurised air only if necessary.
- d)Do not consume, store or process food, beverages or foodstuffs during or close to the cleaning.
- e) Wash and rinse your hands and face thouroughly after cleaning the Electronic Scorint Target (EST).
- f) Seperate strictly protective clothing from other clothing.
- g)Adhere to all applicable safety regulations and applicable regulations for avoiding lead dust on your shooting range.



NOTICE

Heavy pollution

If the Electronic Scoring Target (EST) is too heavily polluted, it cannot register shots. Shots can be missed.

- a) Calibrate the EST before competitions, important phases of competitions and before single positions of competitions.
- b) Verify the values for Amplification.
- c) If levels with medium amplification appear, clean the EST after the phase of the competition.
- d)If levels with maximum amplification appear, clean the EST immediately.
- e) Calibrate the EST again after cleaning.

Clean the perspex screens regularly to

- ensure optimal functioning
- avoid missed shots

Meyton suggests a cleaning every 1000 to 5000 shots and if required.

2 Verification of the EST with Control-PC

Verify if a cleaning of the EST is necessary. Verify the EST

- before competitions
- before important phases of competitions
- before single positions of competitions
- after competitions
- after training

Applicable to ESTs with ESTA-Control and ESTA-Pro.

2.1 Calibrating the EST

If you calibrate an Electronic Scoring Target (EST) the device is configuring for optimal functioning. The values for optimal functioning depend on the parameters of the environment. The EST is calibrating automatically while booting the Control-PC.



NOTICE

Heavy pollution

If the Electronic Scoring Target (EST) is too heavily polluted, it cannot register shots. Shots can be missed.

- a)Calibrate the EST before competitions, important phases of competitions and before single positions of competitions.
- b) Verify the values for Amplification.
- c) If levels with medium amplification appear, clean the EST after the phase of the competition.
- d)If levels with maximum amplification appear, clean the EST immediately.
- e) Calibrate the EST again after cleaning.

Requirement: The program Competition control is open.

a) Select the lanes. Draw the mouse while clicking left over the lanes that you want to select.







	5 W	Printer University 2.4 Md	800
	Date present proofs modulation Degreets metanget doubt and		
	🖂 📽 🐑 🤎 🕐 🛄 💢 📲 thereadersentiates availant		
	Francisco de la companya de la compa	Interest Design Design Design Design Design Design Design Des	
	- He Boll and A	Permanent base bases more accurate terms in the is is it. In a lot is it is is in the intervent in the inter	an province of property of the second
	In LO Auflight 20 10	USANNET PIER I I REER F I I F I I F I I	WIEGOLDS He
	a limiter III		# 5/30,000,000,000
			- WENTER, N-
	C HONOR THINK	10-MBag 20 Page 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	# 912 KH (#5.) # # 970 KH (#5.) #
	NAME OF A DESCRIPTION O		- <u> </u>
	141 CANEL SEL TAILAN		WEINING NO
A Second Se			
A Second Se			
	10		×
present and a pr			NUMBER OF A DESCRIPTION
	and the local set of an independent of the	All the day for a first sector we have	Sector and a sector

Illustration 2: calibrate the measuring frame

c) Confirm the calibration of the ESTs.

8 G			H	andre Weineriger (1.4.)	H					101101
The latest latest and lates	n popula benegat gener gen 2. 🔥 📦 🐋 📇 🔍 📰 🖬									
Verlagence Carter Dr	iani / F. Schites Land	Wolflagen Date	Salary iffar	ter Mot Gasard	Bastanti (12 (14	1 63 64 64 67 6	i da dai tiana	Museu hall	Operation	Enter 240
 Mathematical II U.Configuration II U.Configuratio II U.Configuratio II U.Configuratio II	Hit Algo C Research Hit Algo C Research Hit Algo C Research Hit Contri, and are real Hit Contri, and are real Hit Control, color reads to the real Hit Control Color reads to t	Loi Prese en Coi Antinge III Coi Antinge III	France 17969 17969 17969 17969 17969 17969 17969 17969 17969						V10 (41 (40) V10 (4	
			Do you really want to calibr	Warning rate the frames of the m	arked lanes?While the	8 8				
		4	calbration is running, there must not be changed II Als running!	e must be no objects ins o no hits will be measu Ja	ide the frame and targets fa ed while the calibration is	ces				
	Warmin Landon Kananda 💦 Mada	a Manalan Nol Nel Sec.	and the law in the sheat sector of					polentian barac LHLIM	State at	- 1104
a can anna an			and the second s							

Illustration 3: Confirming the calibration of the EST

Result:

The service mode is active. The ESTs are calibrating.

Display on the Control-PC

During the calibration of the EST the Control-PC is displaying the following screen:

Measurin	g irame	2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	(C) Meyton Electronic umbn
Identifi	ed frame:	MF4/5R3	an an ann an
Returned	light values:	Page:	
Y-Axis:	Adjust amplificat	ion	Relay: 5
X-Axis:	Average:	Std. dev.:	Min.: Max.:
Y-Axis:	Average:	Std. dev.:	Min.: Max.:
Y-Axis:			Relay: 5
X-Axis:	Average:	Std. dev.:	Min.: Max.:
Y-Axis:	Average:	Std. dev.:	Min.: Max.:
Amplific	ation: F1 :	F2 : F4 :	F8 :
Amplific	ation: F1 :	F2 : F4 :	F8 :
Y-Axis:	Determine 100% va	lues	Relay: 5
X-Axis:	Average:	Std. dev.:	Min.: Max.:
Y-Axis:	Average:	Std. dev.:	Min.: Max.:
Y-Axis:	Determine 0% valu	es	Relav: 3
X-Axis:	Average:	Std. dev.:	Min.: Max.:

Illustration 4: Calibration of the EST on the Control-PC

2.2 Reading the display during the calibration



NOTICE

Heavy pollution

If the Electronic Scoring Target (EST) is too heavily polluted, it cannot register shots. Shots can be missed.

- a)Calibrate the EST before competitions, important phases of competitions and before single positions of competitions.
- b) Verify the values for Amplification.
- c) If levels with medium amplification appear, clean the EST after the phase of the competition.
- d)If levels with maximum amplification appear, clean the EST immediately.
- e) Calibrate the EST again after cleaning.

Requirement:	The EST is calibrating
Requirement:	The Control-PC displays the following screen.



Illustration 5: Calibration of the EST on the Control-PC

- a) Verify the values for Amplification.
- b) Verify the values after F4.
- c) Verify the values after F8.
- d) Press the button Competition to leave the screen

The Amplification shows how much the light of a light barrier has to be amplified so that the light-barrier can detect hits. The amplification is measured in 4 levels:

- F1 is the level without amplification
- F2 is the level with the least amplification
- F4 is the level with the medium amplification
- ${\rm F8}$ is the level with the maximum amplification

The display on the Control-PC counts how many light-barriers are in the different levels. The first line is counting the light-barriers on the horizontal axis of the EST. The second line is counting the light-barriers on the vertical axis of the EST. The sum of all numbers is the number of all light-barriers in the EST. The number of light-barriers depends on the model of EST.

A perfectly clean EST has only light-barriers with the amplification F1.

A clean EST has about 90% light-barriers with the level F1 and 10% light-barriers with the level F2.

Lightbarriers with more than 15% level F2 indicate pollution.

Light-barriers with the level F4 indicate heavy pollution.

Light-barriers with the level F8 indicate extremely heavy pollution.

3 Verification of the EST with ESTA5

Verify if a cleaning of the EST is necessary. Verify the EST

- before competitions
- before important phases of competitions
- before single positions of competitions
- after competitions
- after training

Applicable to ESTs with ESTA-Mobile.

3.1 Showing the light sensor values

The menu is open.

Requirement:

- a) Press ON Technical Service Menu.
- b) Press on Sensor Values.

Interim result:

ESTA5 shows the condition of the light sensors.

c) Press on Exit sub-menu to return to the menu.

3.2 Reading the light sensor values



NOTICE

Heavy pollution

If the Electronic Scoring Target (EST) is too heavily polluted, it cannot register shots. Shots can be missed.

- a) Calibrate the EST before competitions, important phases of competitions and before single positions of competitions.
- b) Verify the values for Amplification.
- c) If levels with medium amplification appear, clean the EST after the phase of the competition.
- d) If levels with maximum amplification appear, clean the EST immediately.
- e) Calibrate the EST again after cleaning.
- a) Verify the values.
- b) Count the numbers of the light-barriers in the different levels.

The Sensor Values shows how much the light of a light barrier has to be amplified so that the light-barrier can detect hits. The amplification is measured in 4 levels:

- Good: is the level without amplification
- A Bit Dark: is the level with the least amplification
- Dark: is the level with the medium amplification
- very dark: is the level with the maximum amplification

The display shows how many light-barriers are in the different levels. The lines represent the different axes of the ESTs. The number of light-barriers depends on the model of EST.

A perfectly clean EST has only light-barriers with the amplification Good:.

A clean EST has about 90% light-barriers with the level Good: and 10% light-barriers with the level A Bit Dark:.

Light-barriers with more than 15% level A Bit Dark: indicate pollution.

Light-barriers with the level Dark: indicate heavy pollution.

Light-barriers with the level very dark: indicate extremely heavy pollution.

3.3 Calibrating the EST

Requirement:

The menu is open.

- a) Press on Technical Service Menu.
- b) Press on Calibrate EST.
- c) Confirm with OK.
- d) Wait until the calibration is finished.

Interim result: ESTA5 shows the condition of the light sensors.

e) Press on Exit sub-menu to return to the menu.

4 Cleaning the EST



DANGER

Lead dust

Avoid the creation of and the exposure to lead dust.

- a) Wear protective gloves, protective goggles, protective mask and suitable protective clothing.
- b)Use wet pieces of cloth for cleaning and for absorbing lead dust.
- c) Use a brush and presurised air only if necessary.

brush

- d)Do not consume, store or process food, beverages or foodstuffs during or close to the cleaning.
- e) Wash and rinse your hands and face thouroughly after cleaning the Electronic Scorint Target (EST).
- f) Seperate strictly protective clothing from other clothing.
- g)Adhere to all applicable safety regulations and applicable regulations for avoiding lead dust on your shooting range.

Requirement: Requirement: Requirement:

wet cloth The EST is accessible from the rear

a) Clean the upper surface of the EST with a brush.



Illustration 6: Cleaing the upper surface of the EST

b) Clean all perspex screens with a brush. Do not scratch the perspex screens.



Illustration 7: Clean all perspex screens with a brush

c) Clean all perspex screens with a wet cloth. Do not scratch the perspex screens.



Illustration 8: Clean all perspex screens with a wet cloth

d) Clean the exterior of the EST with a wet cloth.





Result:

The EST is clean.